

## How to carry out simple visual checks on electrical equipment A guide for employees, students and visitors

Users of electrical equipment should check that there are no signs of damage or interference with that equipment before it is used and when it is moved to a new location. A simple visual check can detect the majority of potential problems. These checks also apply to extension leads and associated plugs and sockets. Examples of typical faults or damage<sup>i</sup> are shown below.

## Electricity can kill. Do not take unnecessary chances.

If you are unsure whether any electrical equipment is unsafe or if there are signs that could indicate the equipment is faulty or damaged, <u>DO NOT USE IT and REPORT IT</u> <u>IMMEDIATELY</u>. See Points of Contact - Electrical Safety for details by campus (<u>www.essex.ac.uk/ohsas/electricity</u>).

Points to check	Example photograph	Description of photograph
Damage to the cable sheath (apart from light scuffing)		Outer insulation of the cable is broken. Inner cables or wires are visible.
Damage to the plug casing and lack of insulation on bottom two pins		The plug casing is broken. Also, the bottom two metal pins are fully exposed and have no insulation (black sheathing which covers one half of each bottom pin, closest to the plastic casing of the plug).
Damage to the casing of the electrical equipment		A portable fan with a broken base. Internal connections and wires are exposed.
Signs of unsafe connections		Electrical cable connectors have been used to join two separate pieces of cable in order to extend the overall length of cable.

How to carry out simple visual checks



Damage to cable grip	Outer insulation cable is not gripped inside the plug casing. Internal cables are exposed.
Lost earth connection	The earth wire has become detached from inside the plug casing.
Overloaded socket	An overloaded extension lead which is being used to supply electricity to multi-way plugs and other adaptors.
Overloading and multiple wiring of socket	The wall mains socket is overloaded. Multiple items of electrical equipment have been wired into one plug; this is highly dangerous.
Overloading and wiring of second item of equipment onto pins outside protective casing	Wires are exposed. Two items of equipment are being run off a single plug; this is highly dangerous.
Evidence of overheating	Scorch or burn marks on socket casing due to either a poor connection in the socket or in the equipment which is plugged into the socket



Unsuitable conditions - inside	Electrical weighing machine used on kitchen sink. Potential contact between water and electricity.
Unsuitable conditions – outside	Electrical extension leads used outside in wet conditions.
Unsuitable conditions – poor housekeeping	Electrical cable is likely to be cut by the circular saw.
Overloaded sockets	Multiple appliances connected to inappropriate adaptors, plugs or extension leads
Unsuitable conditions – poor housekeeping	Cables are lying across the floor in front of a doorway. Likely trip hazard.

## Other examples of hazards:

- Trip hazard where cables are covered by carpet or rugs.
- Heavy furniture or equipment with sharp edges is put on top of cables. This could lead to damage to the outer insulation of the cable or wiring inside the cable.

<sup>&</sup>lt;sup>i</sup> Sources of photographs: Maintaining portable and transportable electrical equipment (HSG107) University Safety and Health Association (USHA) http://www.diynot.com/forums/viewtopic.php?p=1784842